

CA7803459

AECL-6095

**ATOMIC ENERGY
OF CANADA LIMITED**



**L'ÉNERGIE ATOMIQUE
DU CANADA LIMITÉE**

**STEAM GENERATOR TUBE FAILURES:
EXPERIENCE WITH WATER-COOLED
NUCLEAR POWER REACTORS DURING 1976**

by

O.S. TATONE and R.S. PATHANIA

Chalk River Nuclear Laboratories

Chalk River, Ontario

February 1978

ATOMIC ENERGY OF CANADA LIMITED

STEAM GENERATOR TUBE FAILURES:

EXPERIENCE WITH WATER-COOLED NUCLEAR
POWER REACTORS DURING 1976

by

O.S. Tatone and R.S. Pathania

Chalk River Nuclear Laboratories
Chalk River, Ontario
February 1978

AECL-6095

Défaillance des tubes de générateurs de vapeur

Expérience acquise en 1976 dans des centrales nucléaires ayant un ou plusieurs réacteurs refroidis par eau

par

O.S. Tatone et R.S. Pathania

Résumé

Une étude a été effectuée au sujet de l'expérience acquise en 1976 avec les tubes de générateurs de vapeur de centrales nucléaires. Sur les 68 réacteurs refroidis par eau ayant été étudiés, 25 ont eu des défaillances de tubes de chaudière. On décrit ces défaillances ainsi que les méthodes conçues pour les détecter et les réparer. Les données recueillies ont permis de constater que la corrosion a été la principale cause des défaillances de tubes de chaudière en 1976. Des améliorations doivent être apportées à la conception des générateurs de vapeur, à l'intégrité des condenseurs et au contrôle chimique de l'eau secondaire.

L'Energie Atomique du Canada, Limitée
Laboratoires Nucléaires de Chalk River
Chalk River, Ontario

Février 1978

AECL-6095

STEAM GENERATOR TUBE FAILURES
EXPERIENCE WITH WATER-COOLED NUCLEAR
POWER REACTORS DURING 1976

by

O.S. Tatone and R.S. Pathania

ABSTRACT

A survey was conducted of experience with steam generator tubes at nuclear power stations during 1976. Failures were reported at 25 out of 68 water-cooled reactors. The causes of these failures and the repair and inspection procedures designed to cope with them are summarized. Examination of the data indicates that corrosion was the major cause of steam generator tube failures. Improvements are needed in steam generator design, condenser integrity and secondary water chemistry control.

Atomic Energy of Canada Limited
Chalk River Nuclear Laboratories
Chalk River, Ontario
February 1978

AECL-6095

CONTENTS

1. INTRODUCTION	1
2. SURVEY OF 1976 FAILURES	2
3. LOCATION AND CAUSE OF TUBE FAILURES	15
4. HISTORY OF TUBE FAILURES	21
5. INSPECTION AND REPAIR PROCEDURES	24
6. SECONDARY WATER CHEMISTRY CONTROL	25
7. TUBE MATERIALS	27
8. SUMMARY	29
9. ACKNOWLEDGEMENTS	29
10. REFERENCES	30
11. APPENDIX I STEAM GENERATOR EXPERIENCE TO 31 DECEMBER 1976	32

TABLES

1. SUMMARY OF STEAM GENERATOR TUBES PLUGGED DURING 1976	4
2. LOCATION OF 1976 FAILURES	16
3. CAUSE OF 1976 FAILURES	18
4. ANNUAL TUBE FAILURES VS. YEAR	22
5. CUMULATIVE TUBE FAILURES VS. EFPD	23
6. SECONDARY WATER CHEMISTRY CONTROL	26
7. EXPERIENCE WITH TUBE MATERIALS TO 31 DECEMBER 1976	28

INTRODUCTION

The performance of steam generator tubes at water-cooled nuclear power plants during 1976 has been reviewed. Data on tube failures, their causes and repair are presented as in previous surveys by Atomic Energy of Canada Limited (1-5). This survey does not include data from reactors in the USSR and Eastern Europe. Nor does it include reactors rated at 50 MW(e) or less except for NPD*. Otherwise, all water-cooled power reactors with steam generators with more than 85 effective full power days (EFPD) at 31 December 1976, were included.

The 68 reactors in this study were of the following types:

- 52 pressurized water reactors (PWR)
- 10 pressurized heavy water reactors (PHWR)
- 5 boiling water reactors (BWR)
- 1 water-cooled graphite-moderated reactor

Eight of the PHWR's were of the CANDU-PHW** design.

Steam generator tubes were plugged at 24 reactors because of failures and at four reactors where tubes were removed for laboratory investigation. A number of tubes were known to be leaking at Garigliano but were not plugged during the reporting period.

More than 60% of steam generator tubes plugged during 1976 had tube constriction at tube support plates (denting). A further 26% of tubes plugged had sustained wall thinning in excess of acceptable or regulatory limits. The thinning was due to corrosion by residual phosphates (wastage) in the zone of accumulated sludge above the tube-sheet. Stress corrosion cracking (SCC),

*NPD - Nuclear Power Demonstration Reactor, Rolphton, Ontario, 25 MW(e).
**CANDU-PHW - CANada Deuterium Uranium - Pressurized Heavy Water

fretting and fatigue also accounted for a significant number of tube failures.

Information for this review was obtained from the literature and from questionnaires mailed to operating personnel of the reactors involved. Approximately 95% of the questionnaires were returned to the authors.

SURVEY OF 1976 FAILURES

Operations are described below for power reactors in which steam generator tube repair was performed during 1976. A summary of these operations is presented in Table 1.

BEZNAU-1, Switzerland

Seven tubes were plugged in Beznau-1 steam generators during 1976. The failures were caused by caustic stress corrosion cracking. Cracks were located within the tubesheet crevice, distributed in a random pattern over the hot leg side. Fourteen tubes showed thinning greater than 20% of wall thickness from the secondary side. These were located on both inlet and outlet legs.

Automated eddy-current testing was performed on 1757 tubes to the first support plate and to the uppermost support plate on 339 tubes. An additional 106 tubes were inspected through the U-bend from the hot leg side. No dent indications were reported. Secondary water chemistry was maintained within specification; no condenser leaks occurred during the year.

BEZNAU-2, Switzerland

Extensive wastage in Beznau-2 steam generators resulted in the plugging of 118 tubes. All defects were within the tubesheet sludge pile and were especially severe on the cold leg side.

More than 3000 tubes in each steam generator were subjected to eddy-current testing to the first support plate. An additional 860 tubes were tested to the top tube support and 174 tubes through the U-bend from the inlet side. No problems due to denting were reported for 1976. In both Beznau-1 and -2 repairs were made by explosive tube plugging techniques.

BIBLIS-A, FRG

The 900 mm tube sections were removed from Biblis-A steam generators for laboratory inspection. The sites were explosively plugged and seal-welded. Eddy-current testing was performed on an additional 1200 tubes.

BORSSELE, Netherlands

A tube was removed from one of the steam generators for laboratory examination; explosive plugs were fitted to 2 tubes because of problems encountered during the operation. Also as part of the testing program remote eddy-current inspection was performed on about 3% of hot leg tubes and 1% of cold leg tubes in each steam generator. No defects were reported.

Seven condenser leaks were repaired during 1976 but no secondary chemistry upsets were experienced. This station is cooled by sea water and secondary water chemistry control is achieved by phosphate addition. No dent indications were reported, but the tube support plates in Borssele steam generators are stainless rather than carbon steel.

Table 1 - SUMMARY OF STEAM GENERATOR TUBES PLUGGED DURING 1976.

REACTOR	TUBES PLUGGED	FAILURE CAUSE	FAILURE LOCATION	SECONDARY CHEMISTRY CONTROL	CONDENSER COOLING WATER	CONDENSER LEAKS	COMMENTS
Beznau-1	7	SCC	TS crevice	AVT	Fresh	No	
Beznau-2	118	W	few in HL many in CI	AVT	Fresh	No	
Biblis A	2	--	--	PO ₄	Fresh	Yes	removed for inspection
Borssele	2	--	--	PO ₄	Sea	Yes	1 removed for inspection, 1 plugging error
Dresden-1	4	UD	outer edge of tube bundle	NR	Fresh		BWR
Garigliano	--	--	--	NR	Fresh	Yes	SSG-A out of service due to leakage but not opened in 1976, BWR
Ginna	56	W,SCC	few cm above TS	AVT	Fresh	Yes	3 tubes caustic cracking, 1 random leak
Haddam Neck (Conn. Yankee)	4	UD	>2.5 cm above TS	AVT	Fresh	Yes	
KRB Gundremmingen	231	corrosion	near divider plate at TS	NR	Fresh	Yes	BWR
KWO Obrigheim	9	SCC	HL near bundle centre above TS, U-bend	AVT	Fresh	Yes	
Mihama-1	2	--	--	NR	Sea	No	removed for inspection, shut-down all 1976
N-Reactor	3	UD	UD	AVT	Fresh	Yes	all leaks in stainless steel tubes.
Oconee-1	6	fatigue	upper TS (on open inspection lane), 14th TSP (not on open lane)	AVT,CD	Fresh	Yes	OTSG
Oconee-2	3	fatigue, fretting	upper TS (open lane), 15th TSP (open lane), 12th TSP (not open lane)	AVT,CD	Fresh	Yes	OTSG
Oconee-3	3	fatigue	15th TSP (open lane), weld at upper TS	AVT,CD	Fresh	Yes	OTSG

TABLE 1 - cont'd

REACTOR	TUBES PLUGGED	FAILURE CAUSE	FAILURE LOCATION	SECONDARY CHEMISTRY CONTROL	CONDENSER COOLING WATER	CONDENSER LEAKS	COMMENTS
Palisades	711	W	3rd & 4th TSP	AVT	Fresh	Yes	cooling towers
Point Beach-2	6	W,SCC	above TS	AVT	Fresh	Yes	
Robinson-2	12	W	1st & 2nd TSP	PO ₄	Fresh	Yes	dent indications in one SG
San Onofre	104	W, fretting	above TS, AVB	PO ₄	Sea	Yes	3 removed for U-bend inspection at AVB, hour-glassing at lower 2 TSP in 2 SG
Sena(Chooz)	4	fretting	AVB	AVT	Fresh	Yes	
Surry-1	968	D,SCC	near tube lane and peripheral wedge areas	AVT	Brackish	Yes	
Surry-2	797	D,SCC	near tube lane and peripheral wedge areas	AVT	Brackish	Yes	
Takahama-2	1	--	--	AVT	Sea	No	removed for inspection
Tarapur-1	1	UD	UD	NR	Sea	Yes	BWR
Tarapur-2	80	UD	UD	NR	Sea	Yes	BWR
Three Mile Island-1	8	fretting	15th TSP	AVT,CD	Fresh	Yes	OTSG
Turkey Point-3	275	D,SCC,W	above TS in HL, between 1st and 6th TSP, U-bend	AVT	Sea	Yes	
Turkey Point-4	351	W,D,SCC	above TS in HL, HL between 1st and 6th TSP, U-bend	AVT	Sea	Yes	6 tubes removed for U-bend inspection
Yankee Rowe	2	W suspected	within 10 cm above TS	AVT	Fresh	No	

D = denting
 SCC = stress corrosion cracking
 W = wastage
 AVB = anti-vibration bar
 TS = tube sheet
 TSP = tube support plate
 HL = hot leg
 CL = cold leg
 UD = undetermined

AVT = all-volatile treatment
 CD = condensate demineralization
 PO₄ = phosphate treatment
 BWR = boiling water reactor
 OTSG = once through steam generator
 SG = steam generator
 SSG = secondary steam generator
 NR = not reported

DRESDEN-1, USA

Four defects of unknown cause were plugged near the tube bundle outer edge in secondary steam generator C. Leaking tubes were detected by hydrostatic testing. Due to installation of new sampling equipment, piping and coolers, secondary steam generator chemistry was not monitored during 1976. There was no secondary water treatment for that year.

GARIGLIANO, Italy

Many tube defects occurred in secondary steam generator A and it was removed from service. However, neither steam generator was opened during 1976. The defects were believed to be caused by stress corrosion cracking (6).

GINNA, USA

One failed tube was plugged during January, 1976. A further 39 tubes were plugged on the inlet side of steam generator A and two tubes on the B inlet. It was suspected that three of the defects in A were caused by caustic cracking. The remainder were plugged because the 40% wall-thinning criterion had been exceeded. During April, primary to secondary leak indications were observed on B steam generator. The leaking tube was identified by eddy-current techniques. Fourteen tubes were plugged. The defects were caused by tube-wall thinning.

During the shutdown early in 1976, an extensive inspection of tubes in both steam generators was performed to evaluate the effect of conversion to all-volatile treatment (AVT) and to verify tube integrity for continued operation.

Eddy-current testing at a frequency of 400 kHz was conducted on all inlet and outlet tubes to the first support plate. In addition, about 200 tubes were examined through the U-bend and large numbers in both steam generators were tested for denting. Sludge height was profiled with low frequency (25 kHz) eddy-current testing. Test results showed that no denting had occurred in Ginna steam generators up to this time. In-line condensate demineralizers were installed during an outage (7,8).

HADDAM NECK, USA

Four tubes were explosively plugged during 1976. The defects were 2.5 cm above the tubesheet or higher. The cause of failure is not known.

Automated remote eddy-current inspection was performed on a large number of tubes to satisfy the regulatory authority. About 1500 tubes were tested at the U-bend, more than 1400 to the first tube support plate, 98 to the fourth support and almost 500 around the U-bend. Phosphate concentrations of 10-20 mg PO_4 /kg water were observed in the secondary water at low power and during shutdown.

KRB GUNDREMMINGEN, FRG

The steam generators at Gundremmingen are tubes with stainless steel. During the period of this survey 231 defected tubes were explosively plugged. Although the failure mechanism has not been established with certainty, it is believed to be corrosion related. All defects were located at the tubesheet, bundle centre, near the divider plate. Leaking tubes were identified by a hydrostatic test.

KWO OBRIGHEIM, FRG

Eight tubes were plugged in steam generator I and one tube in steam generator II. Defects in steam generator I were caused by intergranular stress corrosion cracking from the secondary side just above the tubesheet. The defects were located near the centre of the tube bundle in the hot leg. In steam generator II, the failure occurred at the U-bend in the inner tube row where bend radius is smallest. Repairs were made by explosive plugging. Eddy-current testing was performed on 1000 hot leg tubes in steam generator I and 95 hot leg tubes in II.

MIHAMA-1, Japan

Mihama-1 remained out of service during 1976. The steam generators were flushed with hot water from February to May in an effort to remove residual phosphates. Sections of two tubes were pulled to establish the effectiveness of flushing and to ensure that no further degradation had taken place. The tube sites were blocked by manually welded plugs. Also as part of the testing program, all unplugged tubes in both steam generators were subjected to eddy-current testing throughout their full length. It was established that tube deterioration had not propagated since the last inspection. Steam generators in Mihama-2 were also subjected to 100% eddy-current testing to check for changes following conversion to all-volatile treatment of secondary water. No changes were reported.

N-REACTOR, USA

Three tubes defected in one of the two remaining steam generators that are tubed with 304 stainless steel. The leaking tubes were fitted with

manually welded plugs. Although not determined with certainty, the defects were thought to be caused by stress corrosion. The failure pattern followed that of previous years; only stainless steel tubes have failed at N-Reactor. Remote eddy-current inspection was performed on 206 tubes, 150 in the hot leg, of steam generator 6A, which has Inconel tubes. No defect indications were observed.

OCONEE-1, USA

Six tubes were fitted with explosive plugs in Oconee-1 steam generators during 1976. The defects were evenly divided between the upper tube-sheet and the 14th tube support plate. Two tubes that leaked were found to have circumferential cracks, believed to be caused by fatigue. During the shutdowns for tube repair, 435 tubes were inspected by automated eddy-current testing; a further 1015 were inspected during the annual outage. Fibre optics techniques were used on the open inspection lane and the inside bore of failed tubes.

OCONEE-2, USA

Three tubes failed in unit-2 steam generators and were removed for further examination. One tube showed circumferential cracking to be transgranular. The second tube was pulled to investigate wear at the top support plate and the third to investigate an eddy-current indication at the 12th tube support. About 1000 tubes were inspected during the scheduled shutdown and 134 during the leak outage. Inspection techniques were the same as those used at the other two Oconee units.

OCONEE-3, USA

Tube failures in Oconee-3 consisted of one due to cracking at the uppermost tube support plate and two caused by physical damage at the upper tubesheet. It is believed that defects in all three units are due to mechanical rather than chemical processes.

PALISADES, USA

During the annual outage early in 1976, 102 and 609 tubes were plugged in Palisades A and B steam generators, respectively. Defects were caused by excessive wall thinning at the third and fourth support plates. Tapered interference-fit plugs with an integral consumable lip were secured by TIG welding. Eddy-current inspection was conducted on 100% of inlet tubes and 7% of outlet tubes in both boilers. Denting, present in both steam generators, did not appear to have propagated since the last inspection.

In cooperation with the manufacturer, Consumers Power initiated a tube sleeving experiment which, if successful, could prolong tube life at least until full penetration of the original tube occurred. Ten selected tubes in B steam generator were sleeved with little difficulty during the refueling outage and development work to establish feasibility of large-scale sleeving at the next outage was initiated (9).

POINT BEACH-2, USA

Six tubes were fitted with explosive plugs in the two steam generators at Point Beach-2. One of two defective tubes in A steam generator inlet had a

through-wall penetration caused by caustic corrosion, the rest had thinning in excess of predetermined limits. Eddy-current inspection was conducted on 726 tubes to the first support and 330 around the U-bend on the inlet side of A steam generator and 221 to the first support and 37 to the sixth support on the outlet side. More than 1100 tubes were inspected to the first tube support and 227 around the U-bend in B steam generator inlet. The tubesheets were also photographed to provide an accurate record of plugged tubes. As with other reactors with a previous history of phosphate treatment, phosphates were detected in the boilers during shutdown.

H.B. ROBINSON-2, USA

Extensive eddy-current inspection showed that 12 tubes had wall thinning greater than 50% at the first and second support plates. These were sealed with explosive plugs. Dent indications and defects in tube support plates were found in one steam generator. At Robinson-2 secondary water is treated by the congruent phosphate method, holding the sodium to phosphate molar ratio between 2.3 and 2.6. Denting was less extensive compared to plants using all-volatile treatment.

SAN ONOFRE, USA

At the beginning of the reporting period, San Onofre was shut down for refuelling and modifications. The principle cause of tube degradation was wear at the anti-vibration bars which had exceeded limits in 88 tubes. Three of these tubes were removed for further inspection. Anti-vibration bars with square cross section, installed as part of the modification

program, are expected to reduce or eliminate thinning in the U-bend region. Tube thinning at the tubesheet exceeded 50% of wall thickness in 12 tubes. In all, explosive plugs were inserted into 104 tubes. More than 5300 tubes were subjected to eddy-current inspection at 400 kHz around the U-bend from the inlet side and 1427 were similarly inspected at 100 kHz. Although further propagation of dents was not reported, hour-glassing was observed in the bottom two of four support plates in two of the three steam generators. Secondary water continued to be treated with low phosphate.

During July a primary-to-secondary leak was detected. The leaking tube was identified by hydrostatic test and explosively plugged (10,11).

SENA (CHOOZ), France

Four tubes were plugged because of wall thinning at the anti-vibration bar. Eddy-current inspection at 200 kHz was performed on tubes in the hot and cold legs of steam generator 1 and on the cold leg tubes of steam generators 2, 3 and 4. The purpose of the inspection was to observe tube condition at the anti-vibration bars.

SURRY-1, USA

Denting, stress corrosion cracking and U-bend straining resulted in 968 failed tubes in Surry-1 steam generators of which 17 were through-wall penetrations. Denting was more pronounced in peripheral areas with cracking at some dents. Cracks in the U-bend region were generally located at the inner tube rows where radius of curvature is smallest.

A variety of techniques including eddy-current and tube-diameter gauging were employed through the U-bend of several thousand tubes in an effort to map out the condition of the tube bundle. Explosive plugs were used to effect repairs.

SURRY-2, USA

Nine leaking tubes and 788 others were plugged in unit-2 steam generators. Failures were similar in location and type to those experienced in unit-1.

During removal of a wedge-shaped section of the seventh tube support plate from one steam generator, small cracks and radial growth were detected on the periphery of the plate. It was found, that in spite of the cracks the tubes and support plates were firmly locked together (12).

TAKAHAMA-2, Japan

The reactor was shut down for its first annual outage in September, 1976 with resumption of operation scheduled for April 1977. All tubes in the three steam generators were inspected throughout their length by remote eddy-current techniques. In addition, one tube was removed for further examination. No defects were reported. No condenser leaks were experienced in either Takahama-1 or -2 during 1976.

TARAPUR-1, India

The secondary steam generators at Tarapur are tubed with stainless steel 304L. A leak in one tube, plugged in early 1975 was caused by a previous plug working loose. During July, 1975 a leak was detected in steam generator 1B; it was plugged early in 1976.

TARAPUR-2, India

Late in 1974, 21 tubes were plugged in secondary steam generator 2A and 42 tubes in 2B. Further leakage was detected during 1975 by radio-chemical analysis. Repair undertaken during the 1976 refuelling outage consisted of plugging 80 tubes. Although not well understood, the defect mechanism is thought to be corrosion resulting in pin hole perforations of the tube wall.

THREE MILE ISLAND-1, USA

Three Mile Island is equipped with once-through steam generators. Six tubes were plugged because of fretting wear at the top tube support plate. Two additional tubes were plugged because of wall thinning of uncertain origin at the seventh and eighth tube support plates, the region of nucleate boiling. Both welded and explosive plugs were used.

TURKEY POINT-3, USA

At the nuclear units at Turkey Point, steam generator tube denting was experienced on a scale surpassed only by Surry. In unit 3 steam generators,

136 tubes showed dent indications and were plugged. These were located at all tube support plates in the hot leg; nine were leaking. Cracking due to U-bend straining affected 88 tubes sufficiently that these too were plugged. An additional 51 tubes were plugged because of excessive phosphate thinning above the tubesheet on the inlet side. Explosive plugs were used to make these repairs. An extensive eddy-current testing program, similar in scope and purpose to that performed at Surry, was conducted.

TURKEY POINT-4, USA

Similar experience was obtained with unit 4 as with unit 3 except that phosphate thinning was much less evident and cracking at the U-bend was much more pronounced. Two dented tubes and 31 U-bends were removed for further examination and another 19 showed leakage. In all, 351 tubes were plugged, 52 due to denting, 294 due to U-bend defects and 5 because of phosphate thinning. Inspection similar in scope to that of unit 3 steam generators, but even more extensive, was performed using eddy-current techniques.

YANKEE ROWE, USA

Two leaking tubes, each in a different steam generator, were plugged during 1976. Both defects were located just above the tubesheet and were attributed to the use of phosphates for secondary chemistry control during the early years of operation. No scheduled inspections were performed.

LOCATION AND CAUSE OF TUBE FAILURES

The location of tube failures in 1976 is summarized in Table 2.

TABLE 2 - LOCATION OF 1976 FAILURES

Location	Reactor	Tubes Plugged
Tubesheet	Beznau-1	7
	Beznau-2	118
	Dresden-1	4
	Ginna	55
	Haddam Neck	4
	KRB Gundremmingen	231
	KWO Obrigheim	8
	Oconee-1	3
	Oconee-2	1
	Oconee-3	2
	Point Beach-2	6
	San Onofre	12
	Turkey Point-3	51
	Turkey Point-4	5
Yankee Rowe	2	
Support Plates	Oconee-1	3
	Oconee-2	2
	Oconee-3	1
	Palisades	711
	Robinson-2	12
	Surry-1	968
	Surry-2	797
	Three Mile Island-1	8
	Turkey Point-3	136
	Turkey Point-4	52
U-bend	KWO Obrigheim	1
	San Onofre	88
	SENA	4
	Turkey Point-3	88
	Turkey Point-4	294
Other or Unknown	Ginna	1
	N-Reactor	3
	San Onofre	4
	Tarapur-1	1
	Tarapur-2	80

As in previous years, the defects occurred frequently near the tubesheet and at the tube support plates and less frequently at the U-bends.

The causes of tube failures in 1976 and the number of tubes plugged for each cause are shown in Table 3.

DENTING

Denting is circumferential constriction of tubes by tube support plates. It was the leading cause of tube failures in 1976. Denting was caused by compressive stresses exerted on the tubes by the rapid growth of corrosion products (magnetite) formed on the inner surfaces of the carbon steel support plate holes (13). The problem affected only certain designs of tube support plates. It was most acute at stations using brackish or sea water for condenser cooling, although minor denting has also been observed in stations with fresh-water cooling. Extensive denting was observed in steam generators which changed from phosphate to all-volatile treatment (Surry-1, -2, Turkey Point-3, -4). However, recently (1977) denting was observed in steam generators which have operated only on AVT and used sea water for condenser cooling (Ringhals-2, Maine Yankee, Millstone-2) (14). To a lesser extent denting also occurred in San Onofre which was always operated on phosphate treatment and uses sea-water cooling (5). Sea water can enter a steam generator through condenser leaks. Non-volatile impurities in the sea water can concentrate in the steam generator crevices and form concentrated acidic chloride solutions which can cause rapid corrosion of carbon steel (13). The corrosion product so produced is voluminous and has little protective effect.

TABLE 3

CAUSE OF 1976 FAILURES

Cause	Number of Tubes Plugged	% of Tubes Plugged
Denting	2281	60.4
Wastage	968	25.7
SCC*	74	2.0
Other or Unknown (SCC?)**	336	8.9
Fretting	99	2.6
Fatigue	5	0.1

* This includes both tubes which cracked from the secondary side and those shown to have cracked from the primary side.

** Includes a large number of tubes in BWR secondary steam generators which are suspected to have failed by SCC.

The use of additives to inhibit rapid corrosion of carbon steel in existing steam generators is being evaluated. One manufacturer is proposing to use redesigned type 405 stainless steel tube support plates to prevent denting in future units (15).

WASTAGE

Wastage or tube thinning because of residual phosphates was observed in 1976 in some (but not all) steam generators which had converted from phosphate treatment to all-volatile treatment in 1974-75. Wastage occurred mainly in the sludge zone just above the tubesheet in both hot and cold legs. The change to AVT, and the cleaning of steam generators by lancing and hot flushing decreased the incidence of wastage but did not eliminate it entirely. This suggests that removal of phosphate deposits and sludge from a steam generator is rather difficult in practice.

STRESS CORROSION CRACKING

Stress corrosion cracking (SCC) of Inconel-600 steam generator tubes initiating from secondary (shell) side occurred in Beznau-1, Ginna, KWO Obrigheim and Point Beach-2. In the N-Reactor SCC occurred in steam generators tubed with type 304 stainless steel but not in those tubed with Inconel-600. Most cracks occurred in the hot leg just above the tubesheet. KWO Obrigheim and N-Reactor have always operated on AVT whereas the other stations changed from phosphate to AVT in 1974. It is believed that SCC is caused by free hydroxide (caustic) which may be produced by in-leakage of alkali-forming condenser cooling water or by too high a molar ratio (> 2.85) of sodium to phosphate ions in the steam generator water (16). It is noteworthy that SCC from secondary side occurred

in stations using fresh-water cooling. Fresh waters are usually alkali-forming whereas sea waters are acid-forming (17,18).

In some reactors (Surry-1, -2, Turkey Point-3, -4) the deformation produced by denting resulted in intergranular SCC of Inconel-600 tubes from the primary (tube) side. Leaks occurred within the dented region at tube support plates and at the innermost U-bends. Straining of the small radius U-bends was caused by the inward movement of tube legs because of distortion of the tube support plates.

Leaks at innermost U-bends also occurred in KWO Obrigheim; however, it is not known whether the attack initiated from the primary or secondary side. Schenk has reported that the tube-to-tubesheet rolled joints in KWO Obrigheim showed intergranular SCC initiating from the primary side. The cracks did not penetrate the tube wall (19). Primary side intergranular SCC of Monel-400 tubes has also been observed in the secondary steam generators of Garigliano BWR (6).

The cause of failure of 9% of the tubes was unknown. Many of these failures occurred in the stainless steel tubes of the secondary steam generators of various BWR's. It is possible that the failures were caused by SCC.

FATIGUE

Circumferential cracking attributed to high-cycle fatigue resulted in tube leaks in the once-through steam generators (OTSG) at Oconee-1, -2, -3. Most of the cracks were in tubes adjacent to an open inspection lane near the upper tubesheet or the uppermost plate. It is believed that steam flow

up the open lane caused excessive vibrations in the adjacent tubes and initiated the fatigue cracks. The mode of cracking was transgranular. Units currently under construction do not have this open lane.

FRETTING

Fretting wear of tubes was observed in Three Mile Island, SENA and San Onofre. Fretting in San Onofre occurred at the anti-vibration bars in the U-bend region. Previous reports in this series show that fretting in the U-bend region has been a persistent problem in San Onofre steam generators. Additional anti-vibration bars of different design were installed to overcome this problem.

HISTORY OF TUBE FAILURES

Table 4 shows the historical trend of steam generator tube failures. In the last three annual surveys nearly 40% of the reactors in the survey reported steam generator tube failures. Table 5 shows that the number of reactors with tube failures increased with increasing effective full power days of operation. Whereas none of the reactors with less than 200 EFPD reported tube failures, 81% of the reactors with more than 1000 EFPD had tube failures. A similar trend was shown in previous surveys. This effect of operating time on tube failures is understandable since most failures were caused by time-dependent phenomena such as corrosion, fretting and fatigue. There were only five reactors which exceeded 1000 EFPD with no tube failures. These were KKS Stade (Incoloy-800 tubes, low phosphate treatment), MZFR, Trino Vercellese (Stainless Steel Tubes, AVT) and Pickering-1 and -3 (Monel-400 tubes, AVT).

TABLE 4

ANNUAL TUBE FAILURES VS. YEAR

<u>Year</u>	<u>Number of Reactors in Survey</u>	<u>Reactors With Failures</u>	<u>% of Reactors with Failures</u>
1971*	34	19	56
1972	41	13	32
1973	49	11	22
1974	59	25	42
1975	62	22	35
1976	68	25	37

* Data for 1971 is cumulative to the end of 1971.

TABLE 5

CUMULATIVE TUBE FAILURES VS. EFPD*
TO 31 DECEMBER 1976

<u>EFPD</u>	<u>Number of Reactors</u>	<u>Number With Failures</u>	<u>% With Failures</u>
< 200	5	0	0
200 to 500	11	1	9
500 to 1000	25	13	52
> 1000	27	22	81

* EFPD - Effective Full Power Days

The Inconel-600 tubed steam generators in the N-Reactor (AVT) were also in this category although the stainless steel tubed steam generators in the same reactor have suffered many tube failures. All these reactors use fresh water for condenser cooling. It is possible that corrosion due to adverse chemistry conditions has not occurred in these units because of good design and chemical control. In any case the reasons for the excellent reliability of steam generators in these reactors need further analysis. Information from such a study may be useful in improving the design and reliability of future units.

INSPECTION AND REPAIR PROCEDURES

Most of the operators inspected some of their steam generator tubes during 1976. In general the hot legs of the U-bend steam generators were inspected more extensively than the cold legs. The most common method of inspection was remote-automatic eddy-current technique. Tube diameter gauging was used to monitor denting. Fibre optics was also used to examine tubes in some reactors (Oconee-1, -2, -3).

The tubes were repaired by explosive plugging in many reactors. Manually welded plugs were used in some reactors such as Dresden-1, Mihama-1, Takahama-2, N-Reactor and Palisades. Most operators carried out preventative plugging of tubes with partial wall defects and hence the number of plugged tubes was considerably more than the number of leakers. The plugging criterion varied from reactor to reactor. In the United States most operators plugged tubes with defects exceeding 40% of the tube wall thickness.

SECONDARY WATER CHEMISTRY CONTROL

As indicated in Table 6 a majority of the operators used the all-volatile treatment (AVT) for control of secondary-side water chemistry. In this treatment the pH of the feedwater is maintained between 8.8 and 9.2 if there are copper alloys in the condenser and feedwater heaters (20). If there are no copper alloys in the feed train then a pH of 9.2 to 9.5 is maintained to minimize the corrosion of carbon steel in the system. The pH is controlled by addition of ammonia or morpholine, and oxygen is removed by addition of hydrazine. Full-flow condensate demineralizers are used in all reactors with once-through steam generators. They are also available for use during chemistry upsets in some reactors with recirculating steam generators.

Seven reactors still use the congruent phosphate treatment. Four of these operate with 2-6 mg PO_4 /kg water, a sodium to phosphate molar ratio of 2.0 - 2.6 and have not encountered any tube failures. The other three use 5 - 10 mg PO_4 /kg water after having operated with higher phosphate concentrations between 1972 and 1974. Although tube thinning has been observed in some of these reactors it is not a serious problem and therefore phosphate treatment will be continued in these units. One reactor (Trino Vercellese) used all-volatile treatment during normal operation but switched to phosphate treatment during a condenser leak. The phosphate concentration was 12 mg/kg water and the sodium to phosphate molar ratio was 2.4 to 2.6. This reactor is cooled by fresh water.

Many of the reactors surveyed reported condenser leaks during the year. Table 1 indicates that corrosion-induced tube failures were often associated with condenser leaks. Therefore it is essential to improve the reliability of condensers in order to increase the reliability of steam generators. Reactor vendors and

TABLE 6

SECONDARY WATER CHEMISTRY CONTROL

Reactor	Method	Remarks
Atucha Biblis A Borssele KKS Stade	Phosphate treatment	2 to 6 mg PO ₄ /kg water
Jose Cabrera (Zorita) Robinson-2 San Onofre	Phosphate treatment	5 to 10 mg PO ₄ /kg water
Arkansas-1 MZFR Ocone-1,-2,-3 Rancho Seco Three Mile Island	All Volatile treatment	With full-flow condensate demineralization
Calvert Cliffs Doel-1,-2 Ginna N-Reactor Trojan	All Volatile treatment	Full-flow condensate demineralization available if required
Trino Vercellese	All Volatile treatment	Phosphate addition during condenser in-leakage
Other reactors in survey	All Volatile treatment	

utilities are turning to more corrosion resistant tube materials such as titanium for condensers in sea-water service (21). Titanium tubing will be used in the new sea-water cooled CANDU reactors (22).

Steam generator manufacturers recommend either corrective action within limited time or a shut down, if the chemistry of feedwater or steam generator water goes out of specification. Limits are placed on pH, conductivity and free hydroxide concentration. A method of automatic control of secondary-side water chemistry is also under development (23).

TUBE MATERIALS

The experience with various tube materials is summarized in Table 7. Type 304 stainless steel was used in early PWR's and in the secondary steam generators of BWR's. Stainless steel was superseded by Inconel-600 because of chloride stress corrosion cracking problems, although it has given satisfactory service in some reactors.

Inconel-600 is the most widely used tube material today; however, failures of this material have occurred by the various mechanisms indicated in Table 7. Some of the failure mechanisms (e.g. denting, fretting, fatigue) were related to design rather than material. Failures by stress corrosion cracking and wastage probably resulted from a complex interaction of design, material, and chemistry control. Thus tube material is just of the many factors which influence the tube failure rates shown in Table 8.

Monel-400 has been used in seven CANDU-PHW reactors and so far only two tubes, out of 164,130 tubes in service, have failed. However, many tubes of Monel-400 have failed in the secondary steam generators of Garigliano BWR.

TABLE 7

EXPERIENCE WITH TUBE MATERIALS TO 31 DECEMBER 1976

Tube Material	Number of Reactors	Number of Tubes	Number of Tube Failures	Tube Failure Rate	Failure Mechanism
Type 304 SS	10	55,303	894	1.6%	SCC, W
Inconel-600	41	520,852	11,726	2.2%	SCC, W, D, Fr, F
Monel-400	8	167,700	232	0.14%	SCC, Fr
Incoloy-800	4	35,840	0	0	--

SCC: Stress Corrosion Cracking
W: Phosphate Wastage
D: Denting
Fr: Fretting
F: Fatigue

It has been reported that these failures were caused by intergranular SCC induced by high levels of dissolved oxygen in the coolant.

Although experience with Incoloy-800 is not as extensive as that with other materials, no steam generator tubes of Incoloy-800 have failed in service. One of the reactors with Incoloy-800 tubes (KKS Stade) has now accumulated ~1500 EFPD of operation without tube failures. Kraftwerk Union (KWU) have used Incoloy-800 tubes since 1972. Atomic Energy of Canada Limited will use this material in future steam generators.

SUMMARY

The performance of steam generator tubing continues to be less than satisfactory. Denting has replaced wastage as the leading failure mechanism, although there is reason to believe that better control of secondary water chemistry should arrest this problem. An important part of the solution for future stations seems to be condensers of higher tube integrity, especially at sites using sea or brackish cooling water. Development of steam generator designs which minimize stagnant zones and on-line control of secondary-side water chemistry will also be necessary.

Inspection and repair techniques have been developed to a high degree of effectiveness. These techniques are coordinated with preventative plugging programs during scheduled shutdowns thereby minimizing forced outages.

ACKNOWLEDGEMENTS

The authors acknowledge with gratitude the supportive response of station operating staff around the world, without whose assistance this survey would not be possible. It would be appreciated if any errors or omissions could be communicated to the authors.

REFERENCES

1. STEVENS-GUILLE, P.D., "Steam Generator Tube Failures: A World Survey of Water-Cooled Nuclear Power Reactors to the End of 1971". Atomic Energy of Canada Limited Report AECL-4449 (1973).
2. STEVENS-GUILLE, P.D., "Steam Generator Tube Failures: World Experience in Water-Cooled Nuclear Power Reactors During 1972". Atomic Energy of Canada Limited Report AECL-4753 (1974).
3. STEVENS-GUILLE, P.D. and HARE, M.G., "Steam Generator Tube Failures: World Experience in Water-Cooled Nuclear Power Reactors in 1973". Atomic Energy of Canada Limited Report AECL-5013 (1975).
4. HARE, M.G., "Steam Generator Tube Failures: World Experience in Water-Cooled Nuclear Power Reactors in 1974". Atomic Energy of Canada Limited Report AECL-5242 (1975).
5. HARE, M.G., "Steam Generator Tube Failures: World Experience in Water-Cooled Nuclear Power Reactors in 1975". Atomic Energy of Canada Limited Report AECL-5625 (1976).
6. BUONO, A., D'ANNA, C., MARLUZZI, D. AND STURLA, P., "Esperienze Sui Materiale Impiegati Nelle Centrali Con Reattori Ad Acqua Leggera". Paper presented at XXII Nuclear Congress of Rome, March 24-25, 1977.
7. Docket-50244-502, United States Nuclear Regulatory Commission, "Robert Emmett Ginna Nuclear Power Plant, Unit 1. Reportable Occurrence Report No. R0-76-08: Abnormal Degradation of Steam Generator Tubes". (Rochester Gas and Electric Corp., N.Y. (USA)). March 11, 1976.
8. Nuclear Power Experience, Encino California, Volume PWR-2, Section V.D. Item 75.
9. Docket-50255-502, United States Nuclear Regulatory Commission, "Palisades Nuclear Plant. Annual Operating Report: January-December 1976". (Consumers Power Co., Jackson, Mich. (USA)).
10. "Operating Units Status Report (Gray Book)", United States Nuclear Regulatory Commission Report NUREG-0020-8, August 1976.
11. Nuclear Power Experience, Encino California, Volume PWR-2, Section V.D. Item 100.
12. Nuclear Power Experience, Encino California, Volume PWR-2, Section V.D. Item 90.
13. ECONOMY, G., WOOTTEN, M.J., PEBLER, A.R. and LINDSAY Jr., W.T., "Laboratory Studies of the Denting Phenomenon", Paper presented at NACE Corrosion Research Conference, March 15, 1977, San Francisco.
14. Nucleonics Week, 18(45), p.8, November 10, 1977.
15. MALINOWSKI, D.D. and FLETCHER, W.D., "Update of Operations with Westinghouse Steam Generators", Paper presented at American Nuclear Society, 23rd Annual Meeting, June 12-16, 1977, New York.

16. WEEKS, J.R., "Corrosion of Steam Generator Tubing in Operating Pressurized Water Reactors", Corrosion Problems in Energy Conversion and Generation, edited by C.S. Tedmon Jr., The Electrochemical Society, Princeton, New Jersey, p. 322 (1974).
17. SAWOCHKA, S.G., PEARL, W.L. and PHAM, H.T., "PWR Secondary System Chemistry During Air and Cooling Water Inleakage", Paper No. 76-WA/NE-14, presented at the Winter Annual Meeting of ASME, December 1976, New York.
18. BALAKRISHNAN, P.V., "Effect of Condenser Water In-leakage on Steam Generator Water Chemistry", Paper No. IWC-77-12, presented at the 38th Annual International Water Conference, 1-3 November 1977, Pittsburgh, Pennsylvania. Available as Atomic Energy of Canada Limited Report AECL-5849.
19. SCHENK, H.J., "Investigation of Tube Failures in Inconel-600 Steam Generator Tubing at KWO Obrigheim", Materials Performance, 15, p. 25 (March 1976).
20. SAWOCHKA, S.G., "A Review of Power Cycle Water Chemistry Specifications for Nuclear Steam Generators", Proceedings of the American Power Conference, 38, p. 890 (1976).
21. McCUE, D.M., "Titanium Tubes Cut Costs Even in Average Water", Electrical World, February 15, 1975.
22. TAYLOR, G.F., "Heat Exchanger Tubing Materials for CANDU Nuclear Generating Stations", Paper presented at XXII Nuclear Congress of Rome 24-25 March, 1977. Available as Atomic Energy of Canada Limited Report AECL-5832.
23. LeSURF, J.E., "The Water Chemistry of CANDU-PHW Reactors", Paper presented at the British Nuclear Energy Society. International Conference on Water Chemistry of Nuclear Reactor Systems. Bournemouth, England, October 24-28, 1977. Available as Atomic Energy of Canada Limited Report AECL-5571.

APPENDIX I

Salient parameters and lifetime performance of steam generators are presented in this Appendix.

STEAM GENERATOR EXPERIENCE TO 31 DECEMBER 1976

Reactor	MW(e) Net	# of SG	Tubes per SG	Material	Builder	Area ₂ per SG(m ²)	Condenser Cooling Water	FFPD	Cumulated Defects	Comments
Arkansas-1	820	2	15531	Inconel	BW	12 304	Fresh	464	0	JTSG
Atucha	319	2	~4000	Incoloy	GHH	3 600	Fresh	750	0	PHWR
Beznau-1	350	2	2604	Inconel	W	3 097	Fresh	1731	989	
Beznau-2	350	2	2604	Inconel	W	3 097	Fresh	1513	226	
Biblis A	1146	4	4060	Incoloy	KWU/DBW	4 510	Fresh	512	2	removed for examination
Borssele	447	2	4234	Incoloy	Balcke	3 600	Sea	898	2	removed for examination
Calvert Cliffs-1	850	2	8519	Inconel	CE		Brackish	532	0	
Cook-1	1054	4		Inconel	W		Fresh	462	0	
Doel-1	392	2	3260	Inconel	W	4 130	Brackish	561	0	
Doel-2	392	2	3260	Inconel	W	4 130	Brackish	339	0	
Douglas Point	208	8 x 10	195 x 10	Monel	MLW	97 x 10	Fresh	1612	1	CANDU vertical hairpin
Dresden-1	200	4	1801	SS	FW	605	Fresh	2963	161	
Fort Calhoun-1	457	2	4980	Inconel	CE		Fresh	671	0	
Garigliano	150	2	1785	Monel	KM	560	Fresh	2995	230+	BWR
Genkai-1	529	2			MHI		Sea	433	1	Due to foreign matter
Ginna	490	2	3260	Inconel	W	4 129	Fresh	1530	134	
GKN Neckar	750	3			Balcke/ GHH		Fresh	110	0	
Haddam Neck	575	4	3794	Inconel	W	2 573	Fresh	2492	30	

STEAM GENERATOR EXPERIENCE TO 31 DECEMBER 1976 - cont'd

Reactor	MW(e) Net	# of SG	Tubes per SG	Material	Builder	Area per SG(m ²)	Condenser Cooling Water	EFPD	Cumulated Defects	Comments
Indian Pt-2	864	4	3260	Inconel	W	4 129	Brackish	523	15	
Indian Pt-3	965	4	3260	Inconel	W	4 129	Brackish	134	0	
Jose Cabrera (Zorita)	153	1	2604	Inconel	W	2 308	Fresh	2070	3	
Kanupp	126	6	1355	Monel	B & W(Can)	705	Sea	703	0	CANDU
Kewaunee	540	2	3388	Inconel	W	4 785	Fresh	680	0	
KKS (Stade)	630	4	2900	Incoloy	DBW	2 930	Fresh	1446	2	Removed for examination
KRB Gundremmingen	237	3	1929	SS	VKW	870	Fresh	2651	364	BWR
KWL Lingen	256	2	5000	SS	GHH	2 360	Fresh	1739	112	BWR, amended total
KWO Obrigheim	328	2	2605	Inconel	GHH/Balcke	2 750	Fresh	2356	202	amended total
Maine Yankee	790	3	5703	Inconel	CE	5 405	Brackish	945	0	
Mihama-1	320	2	4426	Inconel	CE	3 381	Sea	646	2206	
Mihama-2	470	2	3260	Inconel	MHI		Sea	904	266	
Mihama-3	780	3		Inconel	MHI		Sea	141	0	
Millstone-2	796	2	8485	Inconel	CE		Sea	250	0	
MZFR	52	2	2113	SS	GHH/Balcke	920	Fresh	2134	0	PHWR
NPD	22	1	2069	Inconel	BW(Can)	577	Fresh	3216	1	CANDU, horizontal steam generator
N-Reactor	790	10 2	1920	Inconel SS	CE	1 486	Fresh	1762	0 27	LGR

STEAM GENERATOR EXPERIENCE TO 31 DECEMBER 1976- cont'd

Reactor	MW(e) Net	# of SG	Tubes per SG	Material	Builder	Area ₂ per SG(m ²)	Condenser Cooling Water	FFPD	Cumulated Defects	Comments
Oconee-1	871	2	15531	Inconel	BW	12 304	Fresh	750	8	OTSG
Oconee-2	871	2	15531	Inconel	BW	12 304	Fresh	548	3	OTSG
Oconee-3	871	2	15531	Inconel	BW	12 304	Fresh	504	3	OTSG
Palisades	700	2	8519	Inconel	CE		Fresh	588	3657	cooling towers
Pickering-1	514	12	2600	Monel	BW(Can)	1 858	Fresh	1594	0	CANDU
Pickering-2	514	12	2600	Monel	BW(Can)	1 858	Fresh	1494	1	CANDU
Pickering-3	514	12	2600	Monel	BW(Can)	1 858	Fresh	1130	0	CANDU
Pickering-4	514	12	2600	Monel	BW(Can)	1 858	Fresh	885	0	CANDU
Point Beach-1	497	2	3260	Inconel	W	4 129	Fresh	1558	362	
Point Beach-2	497	2	3260	Inconel	W	4 129	Fresh	1164	16	
Prairie Island-1	520	2	3388	Inconel	W	4 786	Fresh	672	0	
Prairie Island-2	520	2	3388	Inconel	W	4 786	Fresh	467	0	
Rancho Seco	913	2	15457	Inconel	BW	12 245	Fresh	228	0	OTSG
RAPP-1	207	8 x 10	195 x 10	Monel	MLW	97 x 10	Fresh	480	0	CANDU, vertical hairpin
Ringhals-2	822	3		Inconel	W		Sea	168	0	
Robinson-2	700	3	3260	Inconel	W	4 128	Fresh	1480	97	
San Onofre-1	430	3	3794	Inconel	W	2 573	Sea	2394	182	
SENA(Chooz)	280	4	1662	SS	CO	1 385	Fresh	1956	20	
Surry-1	788	3	3388	Inconel	W	4 784	Brackish	826	1408	
Surry-2	788	3	3388	Inconel	W	4 784	Brackish	769	987	

STEAM GENERATOR EXPERIENCE TO 31 DECEMBER 1976 - cont'd

Reactor	MW(e) Net	# of SG	Tubes per SG	Material	Builder	Area ₂ per SG(m ²)	Condenser Cooling Water	EFPD	Cumulated Defects	Comments
Takahama-1	780	3	3388	Inconel	W	4 784	Sea	579	99	
Takahama-2	780	3	3388	Inconel	W	4 784	Sea	371	1	removed for examination
Tarapur-1	198	2	1600	SS	FW		Sea	1317	2	BWR, amended total
Tarapur-2	198	2	1600	SS	FW		Sea	1304	143	BWR, amended total
Three Mile Island-1	792	2	15531	Inconel	BW	12 304	Fresh	673	8	OTSG
Tihange-1	880	3			CO			362	0	
Trino	242	4	1662	SS	W	1 384	Fresh	2428	0	
Trojan	1130	4		Inconel	W		Brackish	85	0	
Turkey Point-3	693	3	3260	Inconel	W	4 128	Sea	950	309	
Turkey Point-4	693	3	3260	Inconel	W	4 128	Sea	815	515	
Yankee Rowe	175	4	1620	SS	W	1 248	Fresh	4144	65	
Zion-1	1050	4	3260	Inconel	W	4 128	Fresh	564	0	
Zion-2	1050	4	3260	Inconel	W	4 128	Fresh	444	0	

ACRONYMS USED IN THE TABLE:

BW	Babcock & Wilcox	KM	Koninklijke Machinefabrik Stork
BW(Can)	Babcock & Wilcox Canada	KWU	Kraftwerk Union AG
BWR	Boiling Water Reactor	LGR	Water-Cooled Graphite Moderated Reactor
CANDU	Canada Deuterium Uranium	MHI	Mitsubishi Heavy Industries
CE	Combustion Engineering	MLW	Montreal Locomotive Works
CO	Cockerill-Ougree SA	OTSG	Once-Through Steam Generator
DBW	Deutsche Babcock and Wilcox-Dampfkessel Werke AG	PHWR	Pressurized Heavy Water Reactor
EFPD	Effective Full Power Days (calculated from Nucleonics Week 18(4))	SG	Steam Generator
FW	Foster Wheeler	SS	Stainless Steel
GHH	Gutehoffnungshütte Sterkrade AG	VKW	Vereinigte Kesselwerke AG
		W	Westinghouse

The International Standard Serial Number

ISSN 0067-0367

has been assigned to this series of reports.

**To identify individual documents in the series
we have assigned an AECL- number.**

**Please refer to the AECL- number when
requesting additional copies of this document
from**

**Scientific Document Distribution Office
Atomic Energy of Canada Limited
Chalk River, Ontario, Canada**

K0J 1J0

Price - \$4.00 per copy