

# **ANALYSIS OF FUEL OPERATIONAL RELIABILITY AND FUEL FAILURES**

**Ivan Smieško  
SLOVAK ELECTRIC  
NPP JASLOVSKÉ BOHUNICE**

**Prepared for IAEA Regional Training Course  
„WWER Fuel Design, Fabrication, Performance and Back End“  
Bratislava , June 1999**




# Fuel failure

**Loss of fuel rod (cladding) integrity  
Corruption of second barrier  
for fission product release from fuel**

## Consequences

- **Increase of primary coolant activity (operation limit)**
- **Increase of fission product releases to environment**
- **Increase of radwaste activities (Inventory for disposal)**
- **Potential increase of personnel exposure**



# Fuel failure rate defined as

$$R = r.D/N$$

r - number of failed rods per FA (for WWER 1,3)

## WWER Fuel


*~ 0.55 % for Bohunice  
(Martin calculated acco.  
to this equ.)*

**Failure rate 0,005 - 0,008 %**

**Comparable to PWR and BWR results**

**...very good results with regard**

**to limited number of failed fuel PIE's**



# Main causes of fuel failure


- poor fuel design
- inadequate quality control during manufacturing
- poor operational/handling practice

## Only few easily identified leak categories

⇒ Fuel failure analysis is very similar to „criminology“


## Leaks - through wall cracks

- cladding
- end caps
- welds



# Mechanisms of Fuel Failure

- **grid/rod fretting**
- **spacers deformation/rod bowing**
- **primary hydriding**
- **fuel densification**
- **manufacturing (assembling) defects**
- **debris fretting**
- **PCMI**
- **cladding corrosion and deposits**
- **secondary hydriding**



# Spacers Deformation/Rod Bowing

- design deficiency
- rod bowing - very rare cases
- no failures attributed directly to this effect
- WWER 1000 - control rod drop time delays
  - assembly distortion by axial loads beyond design limits


# Fuel Densification/Cladding Collapse

- 1970's - forming of axial gaps in fuel stack
  - modification of pellet manufacturing and pre-pressurization of fuel rods



# Grid/Rod Fretting

- second largest contribution to fuel failures
- potential design deficiency
- loss of metal by mechanical wear
  - sliding, impingement
- thermohydraulics (fluid instability) related fuel assembly or rod vibration
- WWER fuel - different relaxation of SS steel grid and ZrNb cladding - insufficient support of fuel rod in spacer - potential cause of WWER 440 V-230 failures ?
- improved design - Zircaloy spacer grids



# Pellet to Clad Interaction

- closure of gap between pellet and cladding
- iodine induced IGA SCC (axial cracking)
  - slow growth to 60 um depth then acceleration
  - whole process may take only minutes
  - next power ramp may lead to leak
- WWER fuel - excellent resistance
- very low failure occurrence at high burnups
- occurred only at
  - violation of operating rules (power ramps)
  - loop reconnection
- WWER - 1000 - improvement after reduction of permissible cladding defects from 60 to 35 um








FIG. 21. Burnup distribution of discharged (including defective) WWER-1000 FAs [10].


# Debris Fretting

- largest contribution to fuel failures
- common failure mechanism for all reactor types
- circulation of various types of debris - machining chips, others (repair and maintenance operations)
- traps for particles - lower end plate, spacer grids
- rapid fretting leading to wall penetration
- instalation of debris filter - big particles trapped
- particle size reduction - debris failures prevailingly in early stage of fuel operation life
  - positive influence of increased burnup - hard protective oxide layer (harder than base alloy)
- WWER - optimised design - no springs, short spacers, higher coolant velocity, bottom grid as debris filter




# Internal Corrosion

- internal oxidation very low ( $O_2$  liberated by fission)
- hydriding ( $H_2$  pick-up)
  - migration of  $H_2$  from free surface to  $Zr/ZrO_2$  interface - (through microcracks, subgrain boundaries)
  - residual moisture critical (open porosity)
- large variation
  - uniform - no significant consequences arise.
  - „Sunburst“ local patches - (local contamination or depassivation - massive hydriding - stress forming)
    - hydride precipitation perpendicular to stress
- Hydrogen - solubility limit 200 ppm
  - WWER fuel 50-60 ppm real values
  - no evidence of ammonia / hydrazine chemistry influence to increased hydriding




# External Corrosion

- **uniform cladding corrosion - very low**
  - **external corrosion - dark layer 6-8 microns thickn.**
  - **standard water chemistry - anual corrosion rate 0,3-2,9 microns**
- **ZrNb alloy - high sensitivity to free oxygen**
  - **(ZrNbSnFe improved resistance)**
- **nodular corrosion (BWR) - observed occasionally**
  - **causes not clear (repartition and size of second phase particles, impurities Cu, Si,Ca,Mg, galvanic and radiolytic effects)**
- **local boiling (operation limits violation)**
  - ⇒ **not significant problem of WWER fuel**




# Deposit Formation

- **corrosion products**
  - mobilised by chemistry/temperature (solubility) change or „brushing“ by foreign particles
  - decontamination residuals - insufficient flushing
- **impurities (foreign materials - ion-exch. resins, graphite particles e.g)**
- **local deposition enhancement by overheating**
- **preferably at lower parts of fuel assembly**
- **heavy deposit regions - potential pitting initiation**



# Secondary Failures

- appearance in different forms
  - difficulties to identify primary cause
- primary defect - ingress of coolant into fuel rod
  - steam oxidizing cladding and fuel + radiolytic decomposition of steam to hydrogen and peroxide - formation of hydrogen
  - masive hydriding remote (upwards) from primary defect - nucleation centers for cladding cracks - secondary defects



## Secondary Failures - continued

- more damages in upper part of fuel rod (high temperature region)
- very dependent on the primary defect size and less to its position
- small leaks or cracks do not necessarily lead to excessive hydriding - „resealing“ with corrosion products observed
- fabricated (intentionally made) fuel leaks too big - different (unrepresentative) behaviour for operational defects




## Failure cause characteristics

Possible cause	Time of leak appearance	$^{131}\text{I}/^{133}\text{I}$ act. ratio
End caps	Any time	> 1
Primary hydriding	0-60 days	0.5-0.7
Grid-rod fretting	Any time	0.3-0.6
Debris fretting	0-60 days typ.	1.549
PCMI	After power ramp	not exp.
Handling damage	0-60 days	0.3-0.6
Secondary damage	After power ramp	0.741



# Fuel Failure Monitoring

- **during operation**
- **steady state primary coolant activities - global core evaluation**
  - **noble gases - simple chemical behaviour - transport driven by diffusion high volatility - early identification of leak appearance ( $^{133}\text{Xe}$ )**
  - **iodines - more complicated transport mechanisms but by operational experience still applicable**
  - **non-volatile species -  $^{239}\text{Np}$  - large defects indication**
  - **difficulties to distinguish large leaks from tramp uranium**




## **Fuel Failure Monitoring - continued**

- **power transients - iodine spiking - release of fission products from pellet-cladding gap in the defect vicinity**
  - **defect size and location dependent**


## **Leaking Fuel Reloading**

- **currently discouraged -“zero defect strategy“**
- **possible in controlled way (EdF)**
  - **avoid further fuel release into primary circuit**
  - **limitation in defect size (quantitative sipping) and number of reloaded assemblies**
- **experience also in Russia and Ukraine**






# Identification of Failed Fuel Assemblies

- **during operation - limited capabilities to core region or fuel burnup**
  - **flux tilting - not recommended**
  - **$^{137}\text{Cs}/^{134}\text{Cs}$  activity ratio related to fuel burnup**
- **during refuelling - identification of particular leaking assembly**
  - **in-core sipping - suction hood (temperature change) or in-mast (pressure change) - fast**
  - **in-cell (cannister) sipping - temperature and pressure change - more time dependant - more reliable**




## NPP JASLOVSKE BOHUNICE SURVEY OF LEAKING FUEL ASSEMBLIES






## NPP JASLOVSKE BOHUNICE SURVEY OF LEAKING FUEL ACCORDING DISCHARGE TIME



# NPP Bohunice Experience

- on-line gammaspectrometry of primary coolant activity
- different models used for operational data evaluation
- since 1986 in-core sipping combined with cannister sipping
- Totally 48 leaking fuel assemblies identified
  - 46 FA's at V-1 (two WWER 440 V-230 units)
  - 2 FA's at V-2 (two WWER 440 V-213 units)
- Difference V-1/V-2 still not understood
- NPP Dukovany and Paks records similar to V-2
- NPP Loviisa data similar to V-1
- except of one case no reloading of leaking fuel assembly



# **NPP Bohunice**

## **Possible causes of fuel failures**

- **Manufacturing - low number of leaks in 1st cycle**
- **Grid/Rod fretting**
  - **possible explanation of V-1 / V-2 difference (different flow conditions)**
  - **improvement after spacer grids material change?**
- Current status of fuel loading (Zr-SS spacer grids) :**
  - EBO 1 - 283/30    EBO 2 - 236/77**
  - EBO 3 - 342/7    EBO 4 - 277/72**
- **Debris fretting - no possibilities to identify, no supporting arguments from operation, maintenance**







# NPP Bohunice

## Possible causes of fuel failures - continued


- PCI - not probable
  - low failure rate at high burnups
  - only one control assembly found as leaking so far
  - no influence of increased load after refueling
  - no indications from PCI model calculations
  - do not explain V-230/V-213 difference
  - **BUT** - statistically increased leak occurrence at neighbourhood of 6th group of control assemblies
  - **similar results from NPP Bohunice and Loviisa**




# Large Defects Evaluation



# II. BLOK EBO



# IV. BLOK EBO



555

# NPP Bohunice

## Fuel Failures Impact to Plant Operation

- Personnel exposure - still too low coolant activities to observe any effects
- Releases to atmosphere - affected only in short-term periods - resolved by technical measures
- Radwaste activities - activity ratios of long-lived fission products and transuranium radionuclides in V-1 and V-2 evaporator bottoms are well corresponding to ratio of leaking fuel assemblies