

# LEGIBILITY NOTICE

A major purpose of the Technical Information Center is to provide the broadest dissemination possible of information contained in DOE's Research and Development Reports to business, industry, the academic community, and federal, state and local governments.

Although a small portion of this report is not reproducible, it is being made available to expedite the availability of information on the research discussed herein.

**HEALTH AND SAFETY RESEARCH DIVISION**

Waste Management Research and Developments Programs  
(Activity No. AH 10 20 00 0; ONLWCO2)

**RESULTS OF THE INDEPENDENT VERIFICATION  
OF RADIOLOGICAL REMEDIAL ACTION AT  
416 SOUTH MAIN STREET,  
MONTICELLO, UTAH (MS00150)**

J. W. Crutcher and M. J. Wilson

Manuscript Completed — February 1990

Work performed by the  
**POLLUTANT ASSESSMENTS GROUP**

Prepared by the  
**OAK RIDGE NATIONAL LABORATORY**  
Oak Ridge, Tennessee 37831-6285  
operated by  
**MARTIN MARIETTA ENERGY SYSTEMS, INC.**  
for the  
**U.S. DEPARTMENT OF ENERGY**  
under Contract No. DE-AC05-84OR21400

**MASTER** *CP*

# CONTENTS

LIST OF TABLES .....	v
ACKNOWLEDGMENTS .....	vii
ABSTRACT .....	ix
INTRODUCTION .....	1
PROCEDURES .....	2
Objective .....	2
Document Reviews .....	2
VERIFICATION OF REMEDIAL ACTION .....	3
Gamma Measurements .....	3
Soil Sample Analysis .....	3
Radon Measurement Results .....	3
CONCLUSION .....	3
REFERENCES .....	4

## LIST OF TABLES

1	Applicable guidelines for protection against radiation . . . . .	5
2	Results of ORNL analysis of UNC Geotech soil samples from 416 South Main Street, Monticello, Utah (MS00150) . . . . .	6

## ACKNOWLEDGMENTS

Research for this project was sponsored by the Division of Facility and Site Decommissioning Projects, U.S. Department of Energy. The authors wish to acknowledge G. A. Pierce for analysis of soil samples; D. B. Ertel, D. Scott List, and M. E. Mumby for technical reviews; and J. K. Williams and R. F. Carrier for valuable recommendations regarding the content and structure of the document.

## ABSTRACT

In 1980 the site of a vanadium and uranium mill at Monticello, Utah, was accepted into the U.S. Department of Energy's (DOE's) Surplus Facilities Management Program, with the objectives of restoring the government-owned mill site to safe levels of radioactivity, disposing of or containing the tailings in an environmentally safe manner, and performing remedial actions on off-site (vicinity) properties that had been contaminated by radioactive material resulting from mill operations. During 1984 and 1985, UNC Geotech, the remedial action contractor designated by DOE, performed remedial action on the vicinity property at 416 South Main Street, Monticello, Utah. The Pollutant Assessments Group (PAG) of Oak Ridge National Laboratory was assigned the responsibility of verifying the data supporting the adequacy of remedial action and confirming the site's compliance with DOE guidelines. The PAG found that the site successfully meets the DOE remedial action objectives. Procedures used by PAG are described.

**RESULTS OF THE INDEPENDENT VERIFICATION  
OF RADIOLOGICAL REMEDIAL ACTION  
AT 416 SOUTH MAIN STREET,  
MONTICELLO, UTAH (MS00150)\***

**INTRODUCTION**

The mill at Monticello, Utah, was built in 1942 by the U.S. government through the Defense Plant Corporation to provide vanadium during World War II. Various government agencies operated the mill until 1947. In 1948 the Atomic Energy Commission (AEC) obtained the mill and operated it under contract through 1959 to provide both uranium and vanadium. Mill operations were terminated on January 1, 1960. In 1961 the mill tailings piles were leveled and graded, covered with rock and soil, and seeded with native grasses. During 1974 and 1975, the ore stockpiles were removed from the site, and the mill foundations were buried.

The Monticello mill site is a 78-acre tract along Montezuma Creek, south of the city of Monticello, in San Juan County, Utah. The site is bordered on the south and southeast by land held by the U.S. Bureau of Land Management. Other boundaries are the city of Monticello and private property.

During the AEC era, the mill processed approximately one million tons of uranium ore. Vanadium and uranium were the only substances extracted in the milling process. Other constituents of the ore remained in the tailings and were not separated prior to disposal. During the years of active mill operation, the mill tailings were normally moist, so erosion was minimal. However, throughout the mill's operating period, area residents used these tailings as fill material and as aggregate in mortar and concrete.

Under the authority of the Atomic Energy Act, the U.S. Department of Energy (DOE) initiated the Surplus Facilities Management Program (SFMP) in 1978 to ensure the safe caretaking and decommissioning of government facilities that had been retired from service but still had radioactive contamination. In 1980 the mill site at Monticello was accepted into the SFMP, and the Monticello Remedial Action Project (MRAP) was established to restore the government-owned mill site to safe levels of radioactivity, to dispose of or contain the tailings in an environmentally safe manner, and to perform remedial actions on off-site (vicinity) properties that had been contaminated by radioactive material resulting from mill operations. The Monticello mill site and the tailings remain in the custody of the DOE Grand Junction, Colorado, Projects Office. In 1983 remedial

---

\*The verification of remedial action was performed by members of the Pollutant Assessments Group of the Health and Safety Research Division at Oak Ridge National Laboratory under DOE contract DE-AC05-84OR21400 with Martin Marietta Energy Systems, Inc.

actions for vicinity properties were separated from MRAP with establishment of the Monticello Vicinity Properties (MVP) Project.<sup>1</sup>

During 1984 and 1985, UNC Geotech, the remedial action contractor (RAC) designated by DOE, performed remedial action on the vicinity property that is the subject of this report, a vacant lot located at 416 South Main Street, Monticello, Utah. The remedial action plan required excavation of all exterior contamination. When the excavation was completed, the property was resurveyed, including soil sampling, to ensure the removal of all contamination, backfilled with uncontaminated material, and restored to its original condition.<sup>2</sup>

The DOE adopted a policy to assign an independent contractor to verify the data supporting the adequacy of remedial action and to confirm the site's compliance with DOE guidelines. The Pollutant Assessments Group (PAG) of Oak Ridge National Laboratory (ORNL) has been assigned the responsibility of this task at the 416 South Main Street site. This report describes the methods and results of that verification.

## PROCEDURES

### Objective

The objective of the verification activities was to confirm (1) that available documentation adequately and accurately describes the post-remedial-action radiological conditions of the entire property that is to be certified and (2) that the remedial action reduced contamination to within applicable DOE guidelines.

### Document Reviews

Review of the property completion report prepared by UNC Geotech<sup>2</sup> indicates the property was evaluated by the DOE on the basis of Environmental Protection Agency standards<sup>3</sup> and that excess residual radioactive materials were present. Thus it was appropriate to designate this property for remedial action.

The pre-remedial-action survey performed by UNC Geotech identified 159 m<sup>3</sup> (208 yd<sup>3</sup>) of mill tailings 23 to 46 cm (9 to 18 in.) deep. However, during the actual removal process, a total of 168 m<sup>3</sup> (220 yd<sup>3</sup>) of contaminated earth and uranium mill tailings, 23 to 61 cm (9 to 24 in.) deep, were removed.

A post-excavation survey performed by UNC Geotech, consisting of a surface gamma scan with a scintillometer and soil sampling, was performed prior to backfilling of the excavated areas. Samples were taken at each 9.3-m<sup>2</sup> (100-ft<sup>2</sup>) grid block in the areas of excavation, and these samples were blended to form five composite soil samples, representative of the designated areas.



## VERIFICATION OF REMEDIAL ACTION

All measurements presented in this report are gross readings. Background radiation levels have not been subtracted. Similarly, background concentrations have not been subtracted from radionuclide concentrations in soil samples. Applicable DOE guidelines for protection against radiation are given in Table 1.

### Gamma Measurements

Surface gamma exposure rate measurements taken by UNC Geotech from the excavated areas prior to backfilling ranged from 14 to 19  $\mu\text{R/h}$ .

### Soil Sample Analysis

Soil samples representative of the excavated areas were taken by UNC Geotech prior to backfilling. These samples were taken at each 9.3-m<sup>2</sup> (100-ft<sup>2</sup>) grid block and were blended to form five composite soil samples. Analysis by UNC Geotech of these composite samples revealed <sup>226</sup>Ra concentrations ranging from 1.1 to 2.0 pCi/g. These soil samples were obtained by ORNL PAG, and a confirmatory analysis was performed. Results of UNC Geotech and ORNL soil sample analyses are given in Table 2.

### Radon Measurement Results

Radon decay-product concentration (RDC) measurements for this site were determined by the alpha-track method. To monitor radon levels, UNC Geotech placed three Terradex Track Etch<sup>®</sup> detectors at the ground-floor level of the house located on this property for a period of approximately one year (from 1-29-86 to 2-18-87). The average annual working level (WL) of radon progeny concentration, as determined by the Terradex Corporation, was 0.009. This value is below the guideline of 0.03 WL given in Table 1. No RDC measurements were taken in the mobile home that was located on this property at the time of the pre-remedial-action survey because the mobile home was moved from the site after completion of remedial action and prior to radon monitoring.

## CONCLUSION

Results of UNC Geotech soil sample analysis and confirmatory split soil sample analysis by ORNL show that radionuclide concentrations are within applicable DOE guidelines. RDC measurements taken at the ground-floor level of the house located on this property were below DOE guidelines.

Based upon the results of the post-remedial-action data, which are confirmed by the verification assessment data, these radiological measurements fall below the limits prescribed by DOE guidelines. It is concluded that the site successfully meets the DOE remedial action objectives.

---

<sup>®</sup>Track Etch is a registered trademark of Terradex Corporation.

## REFERENCES

1. M. W. Smuin, D. B. Ertel, and H. A. Pfuderer, *Verification of Remedial Actions on Vicinity Properties in Monticello, Utah*, Oak Ridge National Laboratory, ORNL-6556 (Draft), May 1989.
2. UNC Geotech, *Property Completion Report for Monticello Vicinity Property Remedial Action for DOE ID NO: MS-00150-RM, Address: 416 South Main Street, Monticello, Utah 84535*, UNC Geotech, Grand Junction, Colorado, November 1987.
3. *Guidelines for Residual Radioactivity at Formerly Utilized Sites, Remedial Action Program and Remote Surplus Facilities Management Program Sites*, Rev. 2, U.S. Department of Energy, March 1987.

**Table 1. Applicable guidelines for protection against radiation**

Mode of exposure	Exposure conditions	Guideline value
Radionuclide concentrations in soil	Maximum permissible concentration of the following radionuclides in soil above background levels, averaged over a 100-m <sup>2</sup> area <sup>226</sup> Ra	5 pCi/g averaged over the first 15 cm of soil below the surface; 15 pCi/g when averaged over 15-cm-thick soil layers more than 15 cm below the surface
Exposure to <sup>222</sup> Rn progeny	Average annual radon progeny concentration (including background)	0.03 WL

*Source:* Adapted from *Guidelines for Residual Radioactive Material at Formerly Utilized Sites Remedial Action Program and Remote Surplus Facilities Management Program Sites*, Rev. 2, U.S. Department of Energy, March 1987.

Table 2. Results of ORNL analysis of UNC Geotech soil samples from 416 South Main Street, Monticello, Utah (MS00150)

ORNL sample No. <sup>a</sup>	UNC Geotech sample No. <sup>b</sup>	Depth (cm)	<sup>226</sup> Ra concentration (pCi/g)	
			ORNL	UNC Geotech
X1	MAY691	15-30	1.6	1.5
X2	MAY692	15-30	1.9	2.0
X3	MAY693	15-30	1.5	1.2
X4	MAY694	15-30	1.8	1.8
X5	MAY695	15-30	1.1	1.1

<sup>a</sup>An X-type sample is a split of the sample taken by the remedial action contractor.

<sup>b</sup>Soil samples were taken by UNC Geotech at each 9.3-m<sup>2</sup> (100-ft<sup>2</sup>) grid block and blended to form composite soil samples, which are representative of the designated areas.